



Audit - Photos Report			
Factory Name	Xiamen Scent-Sational Enterprises Co., Ltd.	Audit type	Semi Announced Follow-up Audit
Eurofins CPA Office	China	Audit date	May 14, 2025
Customer	BSCI	Report number	CH_EKAI_60


		
Description/Area: Factory gate on the 5F	Description/Area: Factory name	Description/Area: Production building
Comments: Nil	Comments: Nil	Comments: Nil
		
Description/Area: House number	Description/Area: Wax melting workshop	Description/Area: Wax filling workshop
Comments: Nil	Comments: Nil	Comments: Nil

		
Description/Area: Assembly, inspection and packing workshop	Description/Area: Raw materials warehouse	Description/Area: Finished products warehouse
Comments: Nil	Comments: Nil	Comments: Nil
		
Description/Area: Exit sign and emergency light	Description/Area: Emergency light testing	Description/Area: Fire sprinkler system
Comments: Nil	Comments: Nil	Comments: Nil

		
Description/Area: Fire hydrant and fire extinguishers	Description/Area: Fire alarm	Description/Area: Fire hydrant testing
Comments: Nil	Comments: Nil	Comments: Nil
		
Description/Area: Emergency evacuation plan	Description/Area: Evacuation sign in the workshop	Description/Area: Drinking water provided
Comments: Nil	Comments: Nil	Comments: Nil

		
Description/Area: Time recording facility	Description/Area: Toilet in the workshop	Description/Area: Sanitizer and paper provided for the toilet
Comments: Nil	Comments: Nil	Comments: Nil
		
Description/Area: BSCI policy posted	Description/Area: First aid kit	Description/Area: No Burning Sign
Comments: Nil	Comments: Nil	Comments: Nil

		
Description/Area: Suggestion box	Description/Area: Most of electric boxes posted with warning signs	Description/Area: Chemical warehouse
Comments: Nil	Comments: Nil	Comments: Nil
		
Description/Area: MSDS provided and PPE reminding	Description/Area: Eye washing facility	Description/Area: Chemical warehouse
Comments: Nil	Comments: Nil	Comments: NC7.7 Some chemicals without appropriate labels

		
Description/Area: Wax filling workshop	Description/Area: Workshop	Description/Area: Nil
Comments: NC7.7 Some chemicals without secondary container	Comments: NC7.9 Some electric boxes without warning signs	Comments: Nil